




At the Lab. In the Field.
By Your Side.

VVK PUMP CHAMBER VINKOVCI, CROATIA

Page 1 of 1



CONCRETE
WATERPROOFING

QUESTIONS: 1-800-267-8280 or www.kryton.com

BACKGROUND

The Water Works valve chamber situated 4 meters below grade had constant standing water. In fact, the chamber was always filled to the top at ground level. Many attempts to waterproof the concrete chamber were attempted with no success. Waterworks, Croatia was skeptical regarding suppliers claims of waterproofing abilities.

SOLUTION

In April 1998, the Krystol™ Crack Repair Specification No. 1 was installed. The entire chamber was subsequently treated with Krystol™ T1. The chamber has not leaked since. Water Works, Croatia, considers the product application a "Miracle". tanks.

Water Works calls Krystol™ application a "Miracle"



Old concrete dried up after years of water saturation.



Krystol™ repair method stops leaks.

PRODUCT

Krystol™ T1/T2, Krystol™ Plug, Krystol™ Bari-cote

LOCATION

Vinkovci, Croatia

OWNER

Water and Sewage Vinkovci

ENGINEER

Davorin Kuzmanovic

CONTRACTOR

Palir, Zagreb

DISTRIBUTOR

The Crystal Group, LLC

PROJECT CASESTUDY

The Kryton Group of Companies.

1645 East Kent Avenue, Vancouver, BC Canada V5P 2S8 Tel.: 1-604-324-8280 Toll Free: 1-800-267-8280 Fax: 1-604-324-8899 E-mail: info@kryton.com Web: www.kryton.com